

TECHNICAL SERVICE BULLETIN

NO. 74-A-1



Austin MG

March, 1974

SUBJECT:

CONNECTING RODS

MODELS:

1275 CC "A" SERIES ENGINES
1800 CC "B" SERIES ENGINES

This Service Bulletin supersedes #73-A-4, which should be destroyed.

Connecting rods for the above engines supplied as service replacements are equipped with hexagonal nuts for transit purposes only. When fitting replacement rods, the hexagonal nuts MUST be discarded and replaced by the correct nuts, as follow:

1275 cc "A" Series Engine (Midget) Part No. AEG 147

1800 cc "B" Series Engine (MGB) Part No. 13H 5872

AP/IE/3/74